

Product/Process Change Notification PCN # 073115-B044

Product:	PCI Micro Slot; Straddle Mount Connector		Part Numbers Affected:	B044-1202-01X-Z
Issue Date:	July 31, 2015			
Page(s):	1/1			
Distribution:	Active and Contract Customers			

Subject: Change in Insulator Appearance - Vendor change due to worn tooling and supply chain issue.



1. Post July 2015 Insulator Color is whiter in appearance.
2. Post July 2015 Lot Codes are maintained internally by SMP and not ink labeled on part
3. Pin #1 identifier is not molded into part; Non - symmetry of part only allows attachment to PCB in one orientation only.

Product Line Implementation Date: All orders shipped after July 31, 2015

Product Specification: No change to product specification.

Last Order Entry Date : N/A

For questions regarding this PCN contact:

SMP Technology Inc
 Product Manager
 Tel : 831-438-9191
 Email : sales@smp-tech.com