

Product/Process Change Notification PCN # 100118-F215

Product:	FFC .80 mm Pitch ; Right Angle Mount; Surface Mount; Top & Bottom Contact Connectors		Part Numbers Affected:	F215-XX22-300-Z F215-XX22-400Z
Issue Date:	Oct 1,2018			
Page(s):	1/1			
Distribution:	Active and Contract Customers			

Subject: Discontinuance of Product - Insulator Mold Tooling is badly worn and cannot product quality parts .

<p>Discontinued Parts: F215-xx22-300-Z and F215-xx22-400-Z Where XX is Circuit Number (Size)</p>	<p>Replacement Parts: F215-XX2E-300-Z (Top Contact) F215-XX2E-400-Z (Bottom Contact)</p>
---	---

Product Line Implementation Date: All orders shipped after October 1, 2018; There will be no last order date due to the above reason; SMP reserves the right to terminate production at any time at its own discretion. SMP will make every effort to meet customer order requirements.

Last Order Entry Date : N/A

Product Specification: No change to product specification.

For questions regarding this PCN contact:

SMP Technology Inc
Product Manager
Tel : 831-438-9191
Email : sales@smp-tech.com